




|                 |         |      |        |      |          |      |           |             |
|-----------------|---------|------|--------|------|----------|------|-----------|-------------|
| GEN. TOLERANCES |         |      |        |      |          |      |           |             |
|                 | 0.5 - 6 | ±0.1 | 6 - 30 | ±0.2 | 30 - 120 | ±0.3 | 120 - 315 | ±0.5        |
| GEN. MACHINING  | ✓       |      | 1.6    | ✓    | 3.2      | ✓    | 6.3       | ✓           |
|                 |         |      |        |      |          |      | 12.6      | ✓           |
|                 |         |      |        |      |          |      | 25 ROUGH  | ✓           |
|                 |         |      |        |      |          |      |           | ✓           |
|                 |         |      |        |      |          |      |           | ±2          |
|                 |         |      |        |      |          |      |           | 4000 - 8000 |
|                 |         |      |        |      |          |      |           | ±3          |

[illegible]